



Phone 0800-001-931

HASELL CHECKS- TO BE USED WHEN DOING UPPER AIR WORK.

H – Height must be sufficient to recover by not less than 2500 feet AGL

A – Airframe- State entry configuration.

S – Security – no loose articles – harness secure.

E – Engine. Temp and pressure in the green. , fuel sufficient and on both.

L – Location. Not over populated areas.

L – Lookout. Carry out minimum 180 degree clearing turn. 360 degree preferably.

In between stalls use HELL checks.

H – Height must be sufficient to recover by not less than 2500 feet AGL

E – Engine. Temp and pressure in the green, fuel sufficient and on both.

L – Location. Not over populated areas.

L – Lookout. Carry out minimum 90 degree clearing turn. 180 degree preferably.